



Main datas

Builder : Fairline
Year : 1992
Length : 18,90
Draft : 1,50
hull : Monohull
Area : France Med
Berth details : VOIR AVEC LE PORT
Flag : France

Subtype :
Architect :
Material : GRP
Beam : 5,28
keel : Unknown
Life Raft : Yes
Mooring : Yes
Leasing in progress : No

Engines

Brand : Man diesel
Montage : In Board (IB)
Power Unit. (CV) : 1000
Shaft : Shaft drive

Brand : Man diesel
Fuel : Diesel
Comments : The engines have been submitted for refurbishment carried out by professionals of the MAN brand, they are now guaranteed for 3 years, the 2 reversers have received a complete overhaul, all hoses, seals, filters, exhaust hoses have nine, the generator has been thoroughly revised by a pro, all invoices are available, the air conditioning has been revised, filters changed in accordance with the rules of the art professional work,

Facilities

Sailor Cabin : 2
WC : Electric
Helm : Yes

Double Cabin : 3
Head : 3
Flybridge : Yes

Electronics

Radar details : RAYMARINE
Sounder details :
Plotter details :
Watermaker details :

Radar : Yes
Autopilot : Yes
GPS : Yes
VHF : Yes
Watermaker : No

Bridge equipment

Hydrolic Gangway : Yes
Bath platform : Yes
Winter cover : No
Furling mainsail : No
Sails details :
Teak cockpit : Yes

Gangway : Yes
Davits : No
Electric windlass : Yes
Furling genoa : No
Spinnaker : No
Teak deck : No

Major equipment

Stern thruster : No
Group and thruster details : ONAN EQD
Charger and AC details : serviced 2020
Tender : No
Details :

Bow Thruster : Yes
Marine Gen. : Yes
AC : Yes
Flaps : Yes
Tender Engine : No

Appliances

Freezer : Yes

Microwaves : Yes

Oven : Yes

Heating details : CLIM REVERSIBLE X 2

Heater : Yes

TV : Yes

TV antenna : Yes

SAT-TV : No

IceMaker : Yes

Oven : Yes

Electric stove : Yes

SAT-TV : No

Divers

Comments : Full option for this magnificent Fairline SQUADRON 62,
a multitude of equipment: New sunbathing, new hydraulic gangway, deck saloon, double converter, new battery pack
2020, flybridge upholstery covers in perfect condition,
new liferaft, LED lighting, with almost new motorization, it is a matter to be seized quickly,







